DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kenneth Tatara APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 3/26/03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #60 Idlewood PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8"	Brn SCL	GR FR					
		8"-30"	Rd/Rd-Brn L/C	m-wSBK	SS,SP,SE,FR				PS
		30"-37"	Yel/Brn C	w.SBK	-massive	SS,SP,SE,			
		37"-48"	Rd/Brn L	wSBK	SS,SP,SE	FR w/Few			.3
				to many	SAP	Inclus			
2		0-10"	Brn SCL	GR FR					
		10"-30"	Rd/Brn C/C	m-wSBK	SS,SP,SE	FFR			PS
		30-48	Rd/Brn	C/C w/	Few Brn to Yel/Brn				
			Mottles	Some	Rock fragments				.25
3		0-8	Brn SCL	GR FR					
		8-30	Rd/Brn C/C	m-wSBK	SS,SP,SE,FR				PS
		30-48	Rd/Brn SC/C	m-wSBK	SS,SP,SE,FR				.3 to
			w/Few	to many	Yel/Brn				
					Mottles				.25
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____