COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: _____ APPLICANT: _____

...RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-6-01

...POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

...ATION OF SITE: SFE's Templeton Farms PROPERTY RECORDED: _____

...ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

...LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

...E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
41-1 SFE 42A	0-5	gr brwsl	frssp					.2
	5-33	sbk RC	fr sp	few ind sap				
	33-50	mas RYL	cl sap	frssp				
41-2 SFE 42A	0-4	wk sbk brwn sal	frssp					.3
	4-24	sbk rc	fr sp ssp					
	24-42	wk sbk gyrd	few common ind sap-frssp					
42-1	0-5	gr brwsl	frssp					.3
	5-30	sbk RC	fr ssp sap					
	30-46	msbk R-yr	cl frssp	few common ind sap				
42-2	0-10	gr brwsl/sal	frssp					.3
	10-31	sbk RC	fr sp ssp					
	31-51	m-wk sbk yrcl	fr-fr sssp	common ind sap				


DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...able Space (.1945)		
...n Type(s)		
...TAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____



120.00'
120.00'
867.12'
97.72'
39S
14,223 S.F.
120.00'
36S
14,400 S.F.
120.00'
120.00'
120.00'
40S
14,400 S.F.
120.00'
37S
14,400 S.F.
1N
42SH
27,140 S.F.
337.72'
120.00'
120.00'
120.00'
41S
14,400 S.F.
120.00'
38S
14,400 S.F.
97.99'
195.99'
97.99'
SIDE SB
120.00'
80.00'
100.00'
40' REAR SB
43
222.15'
44
28,727 S.F.
247.70'
15' SIDE SB
294.61'
314.44'
DRIVE
DRIVE