1969

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Randy Hord DATE 12/7/88 PERMIT NO. 21A

PHONE: Business _____ Home 525-5317

LOCATION 21 S. X I-77 proceed onto 1109 TL b/f lake onto SR 1191 (Ponderosa Blvd.) ~1/4 mile on Rt. S. R. No. _____

SUBDIVISION NAME Bonanza LOT NO. 1 SECTION OR BLOCK NO. II

4646-43-0812

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit — Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ P. S. Yes (✓) No ( )

Lot Area _____

Character & Porosity of Soil Clay
Percolation Rate ~.35 gal/ft²
Topography ~6%
Depth to Water Table 4'+
Rock or other impervious formations none observed

✓ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

1250 gallon pump tank

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 5
Sq. Ft. _____ Linear Ft. 370
Depth of Stone in Lines 1110
Water Supply: Individual (✓)
Public ( )

Installed by F. J. Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

~~IMPROVEMENTS PERMIT BY~~ DRH

COMMENTS: Alarm checked, not mounted.

CERTIFICATE OF COMPLETION BY Andre C Pierce DATE 12/7/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold