4646-44-4280

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR DAVID SMITH DATE 2/10/88 PERMIT NO.

PHONE: Business Home

LOCATION 1109 TR 1191 (PONDEROSA CIRCLE) ~ 1/8 mi. ON RIGHT S. R. No.

SUBDIVISION NAME BONANZA LOT NO. 8 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 4 No. Bathrooms 3 1/2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable PS - Yes (✓) No ( )

Lot Area 30000

Character & Porosity of Soil Shallow clay (silty trans to P.M)
Percolation Rate 2.3 - 35
Topography 4 - 10%
Depth to Water Table 3'+
Rock or other impervious formations sap ↑ w/ depth on lakeside

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement (✓) SPLIT SYSTEM



Plot of System

Size of Tank 1500 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 1080 Linear Ft. 360
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

faked

Installed by F.J. ERVIN

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

WASHER SYSTEM:
75 gal washer tank
150 linear ft of line @ in a 6' x 75' BED.

IMPROVEMENTS PERMIT BY DRH,

COMMENTS: System for washer put in bed due to limited space. 51' from high water mark. Installed Shallow.

CERTIFICATE OF COMPLETION BY Audie C. Queen DATE 2/10/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold