DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Horton
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____
LOCATION OF SITE: Dogwood Harbor LOT 74

APPLICATION DATE: 10/5/06
DATE EVALUATED: 10/16/06
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2-3%	0-12	SCL, wk fsbk	vfr ss sp ss		48"		None	.3
		12-36	RC, m ms bk	fr ss sp ss					
		36-48	BCl, w ms bk	vfr ss sp ss					
2		0-14	SCL, wk fsbk	vfr ss sp ss		48"		None	.3
		14-36	RC, m ms bk	vfr ss sp ss					
		36-48	bcl, wk ms bk	vfr ss sp ss					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	5	PRE 1983
System Type(s)	Pump to Cur	Recorded
Site LTAR	25% Red (P.S.)	LOT

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): Drou. Sw. Hist
EVALUATED BY: Jon Ashley
OTHER(S) PRESENT: _____

COMMENTS: _____