DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: ____ OWNER: ____ AGENT: ____ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 4-4-94
PROPOSED FACILITY: SFR
PROPERTY SIZE: ____
LOCATION OF SITE: Gibbs Cove lot 1
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS	HORIZON LTAR
Front 1 under P/L R/W	knoll - sls 2-4%	0-3	cl / wk med gran	mfr	>49"	>49"	P	—	0.3
		3-25	c / med-wk med sbk	mfi			—	—	
		25-47	c / wk med sbk	msfi					
		47-49	Saprolite						
Back 2 under P/L R/W	ss 6-8%	0-5	cl / wk med gran	mfr	>48"	>48"	P	—	0.3
		5-24	c / wk med sbk	mfi-msfi			—	—	
		24-42	cl / wk med sbk-gran	msfi-mfr					
		42-48	saprolite	mfr-mvfr					
3	ss 4-6%	0-2	c. ___	—	>44	>44	P	—	0.3
		2-14	c / wk med sbk	mfi				—	
		14-27	cl / wk med sbk-gran	mfr					
		24-44	saprolite	mvfr					
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE ____
EVALUATED BY: ____ OTHER(S) PRESENT: ____
COMMENTS: ____