DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Rockcastle

Paid $200

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

4646-89-9417

OWNER: Jason Phillips APPLICANT: Same
ADDRESS: 172 Sunfish Dr. Mount. APPLICATION DATE: ___ DATE EVALUATED: 2/3/04
PROPOSED FACILITY: Home 3-2.5 PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: ___
LOCATION OF SITE: 1100 TL Sunfish Dr. on (R) across from #165 PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LS 4-5 RT, FRT.	0-11	Fr SBK / l-scl	VFR - SS - NP	wet PS / BR				
		12-29	SBK / MIC. cl	FR SS - SP	PS / R				
		30-40	MSBK / c FEW CH3	Fr SS - SP	PS / R				
		41-50	SBK / cl	Fi SS - SP	S / R	S	PS	N/A	.3
2	LS 4% LT FRT.	0-12	SM SBK / l-scl	VFR - SS - NP	wet				
		13-31	SBK / lcl	Fr SS SP	R				
		32-49	SBK / cl SAP	FR MIC SS - SP	PS / RB	S	PS		.3
3	LS 6-8 Inv. Rear	0-8	SBK / l		wet				
		9-26	MA SBK / c	Fi SS-SP	R				
		27-39	LG. SBK / c	Fr MIC SS-SP	R				
		46-49	SBK / MIC cl	FR SS - SP	R				.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Ty 3	16" PPBPS
Site LTAR	.3	.3

OTHER FACTORS (.1946): Rolling Topo / Rain last night
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Sparks
OTHER(S) PRESENT: Jason Phillips