4649491118

10446

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Raymer Oil DATE 10/15/90 PERMIT NO. 2H-5-A-151, 151A, 151-C, 121 ~124

PHONE: Business _____ Home _____

LOCATION 21 S On right at jct. with Waterlynn Rd.

_____ S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

Daily Design Flow 600 gal/day


House ( ) Mobile Home ( ) Business (✓) Other Convenience Store/ Service Station/ Food Stand 2 restrooms, 2 employees Min. food stand floor

No. Bedrooms _____	No. Bathrooms _____			Character & Porosity of Soil	PS clay
Garbage Disposal Unit	Yes ( )	No (✓)		Percolation Rate	~.4
Auto. Dishwasher	Yes ( )	No (✓)		Topography	2-8%
Auto. Wash. Machine	Yes ( )	No (✓)		Depth to Water Table	41+
Site Suitable	Yes ( )	No (✓)		Rock or other impervious formations	none obs.

Lot Area Existing

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement

Easement recorded for repair



Plot of System

Size of Tank 1250+ Gals.

Nitrification Field:

No. of Lines 7

Sq. Ft. _____ Linear Ft. 500'

Depth of Stone in Lines _____

Water Supply: Individual (✓)

Public ( )

Installed by Foothills Plumbing

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

Single Service Min Floor Space Food Stand

Grease interceptor under sink

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Sam Ingram EHS DATE 10/15/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold