IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Bean Building Co.

ADDRESS:

DATE REQUESTED: 3-25-80

COUNTY: Iredell

PLAT NO.:

LOCATION OF SITE: 215 Ron 1135 Ron 1289 ~500 ft. on Rt. Regal Oaks lot 20

LOT SIZE: 100' X 200'

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U — 6-8%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U — loamy-clayey	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S (PS) U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
SITE CLASSIFICATION*	PS.			
SOIL SERIES	Cecil g.m.			

S - Suitable PS - Provisionally Suitable U - Unsuitable

See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments:

Described By: [illegible]

Title: SI

Date: 3-25-80

Form 2601 (2/77)
Location