DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jeff Pelchat — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 8-9-
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Lot 12 Trumbull — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1941 RESTR HORIZ	PROFIL CLASS & LTAR
1	L 4-6%	0-3	gr scL	fr					
		3-24	sab pbrn cl cL	fr sp					
		24-48	ol sab pbrn, cL sap	fr					
			1 PP soil depth .175						
2	L 4-6%	0-14	sa lo vfr brn cl sp	fi sp sap					PS .175-.3
		14-48	m-vcsab pbrn cl						
			few mang mot						
			numerous chk mottles						
3	L ~6%	0-7	gr brn scL	fr					PS .3 @ 32"
		7-22	sab lgr pbrn c/hvy	fr sp sap					
		22-36	sab brn cl few/dis	chk mott fr sp ss sp sap					
		36-48	vfsab brn c/ygc/sgrn						
4		0-5	sab brn scL	fr					PS .3 @ 42"
		5-12	sab RC	fi sp sap					
		12-25	sab brn cL	fr ss sp sap many brn mott					
		25-42	gr-vcsab brn scL	fr sp sap					
		42-48	gr PGRN sL sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

#5 0-10 gr brn scL fr ; 10-36 sl affected fi sp sap subsoil sap 36 11/16 ...