4647901665

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR DONALD L. BLACKWELDER DATE Aug 26, 88 PERMIT NO. _____

PHONE: Business _____ Home 664-6315

LOCATION 21 S. TR 1100 TL Sunfish Out

_____ S. R. No. _____

SUBDIVISION NAME Clippers Run LOT NO. 33/34 SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Clayey
Percolation Rate ~.4gpd/ft²
Topography 2-9%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

Lot Area 4A.

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1500 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (X)
Public ( )

Installed by Caldwell

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY ACP SUNFISH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Rowe DATE 8/26/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

7140

~3:30

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donald L. Blackwelder DATE 7-30-87 PERMIT NO. _____

PHONE: Business _____ Home 664-6315

LOCATION 21 S. TR on Brawley School Road. TL on Sunfish. Property lies at corner of Brawley Rd & Sunfish Rd. S. R. No. _____

SUBDIVISION NAME Clippers Run LOT NO. 33 & 34 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Character & Porosity of Soil clayey
Percolation Rate ~ 4 gpd/ft²
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area ~4 acres

___ Basement with Plumbing ✓ Basement without Plumbing ___ No Basement



SUNFISH DR. Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by (Caldwell)

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Donald L. Blackwelder

IMPROVEMENTS PERMIT BY Andrew C. Price DRHayley RS

COMMENTS: Run lines in front of house along contour / on grade. Maximum trench depth 24" Stay away from right of ways of road

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold