DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Mike Krom OWNER: ✓ AGENT: ___ PHONE: 704 664 3671
ADDRESS: 19 Yacht Cove APPLICATION DATE: 10/21/93 DATE EVALUATED: *
Mooresville NC 28115 PROPOSED FACILITY: SFD
PROPERTY SIZE: ____
LOCATION OF SITE: Mills, Forest II 2
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ✓ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
PIT 8		0-2	l + litter						
		2-24	clay / wk sbk	dvh			P		.03 - .25
		24-28	cl / wk sbk	dh			P		.25
		28-60	l		>60"	>60"			
2		0-2	l + litter						
		2-25	clay / wk sbk	dvh			P		0.3 - .25
		25-33	cl / wk sbk	dh			P		.25
		33-38	l / sbk-gran						
3		0-14	clay / wk sbk	dh					
		14-23	cl						
		23-36	l; clay skins + peds						
			/ sbk	dh					
7 8		@ 12"	clay	dvh / wss + wp					
		@ 21"	scl / mod-wk	wss + wp					
		@ 25"	mscl / wk	wss-wns + wp					
		Rock Fragments and saprolite that is resistant to augering beginning ~ 20"							
		unable to auger beyond 25"							
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____
EVALUATED BY: A.L. OTHER(S) PRESENT: Mike Krom
COMMENTS: evaluations made in October on three separate visits