DIVISION OF ENVIRONMENTAL HEALTH:
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Joseph Tatton APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9/26/00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12"	Brw SCL	GR FR					PS .25 .3
		12"-34"	Rd CL	MSBK	FSSS,SPSS				
		34-48"	Rd/Brw Cl w/ and/or	Organic	some Black staining MSBK SS,SPSS			FD	
2		0-10"	Rd/Brw Cl w/ lots Mica						PS .25
		10"-36"	RC	mSBK S,PSS	F				
		36-48"	Rd/Brw Cl w/ moist		Black staining				
3		0-15	Rd/Brw Cl w/ lots of Mica						PS .35
		15-26	Brn to Rd Brn SCL						
		26-48	RC mSBK with some staining - moist				back		
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Joseph Tatton APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9/27/00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Barefoot Bay Lot 15 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-21	Brw GR SL						PS .25 for 36" TB
		21-29	Rd/Brn C/C mSBK	SS,SP,SE	F-FP				
		29-45	Rd/Brn C/SC wSBK	F,S-SS,SP,SE					
			Mag. Stains @ 41-46"		Low Chroma 57"				
2		0-21	Brw BF SL						PS .25
		21-31	Rd/Brw C/C mSBK	SS,SP,SE	F-FP				
		31-40	Rd/Brn C/SC wSBK	F,S-SS,SP,SE					
			mag. staining at 36" low chroma at 50"						
3	Boat Pit	0-7	Rd/Brw C w/Mag	Probably Fill					PS .25-.3
		7-17	Rd/Brn to Brw GR SL						
		17-36	Rd/Brw C/C mSBK	SS,SP,SE	F-FP				
		36-50	Rd/Brw C/SC wSBK	SS,SP,SE	F-FP				
			48+ Low Chroma	Mottles, Mg. staining					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____