PIN# 4648-22-9150

IREDELL COUNTY HEALTH DEPARTMENT

12823

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charles Bickerstaff DATE 9/5/91 PERMIT NO. 21-8-12

PHONE: Business _____ Home _____

LOCATION Beech Tree Rd, Brawley TR on Beech Tree, 1/4 mile TL, corner lot on (R) S. R. No. 1234


SUBDIVISION NAME Beech Tree Forest LOT NO. 12 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	P - clay - chroms. - (ss)
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	3% to
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	>48"
			Rock or other impervious formations	None observed

Lot Area 20,000 FT²



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4 - 90, 110, 100, 100
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Frye Grading

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: After finish grading - cover over trenches to be no more than 24" over any trench. Driveway must be kept off end of drainlines. D/B no speed levelers - lowest trench slightly ~~less~~ less load than other trenches

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 9/5/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold