DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____ OF____
PROPERTY I.D.#:____
PROPERTY RECORDED:____
COUNTY:____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Jack Johnson OWNER: X AGENT:__ PHONE:____
ADDRESS:____ APPLICATION DATE:____ DATE EVALUATED: 11/25/94
PROPOSED FACILITY: 3BD - crawl Space
PROPERTY SIZE: 1.8 AC
LOCATION OF SITE: Lot 12 Beaufort Bay on Dutch cul de sac starts
WATER SUPPLY: On-Site Well X Comm. Well__ Public__ Other____ EVAL. METHOD: Auger Boring X Pit__ Cut__

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
in front of house 1	~CV NS 3%	0-7	WK GR / sl	I:I / NS NP					.35
		8-21	SBK / cl	I:II / SS SP					
		22-40	GR / cl SAP	I:I / NS NP					
2 de L Area needed	cc	0-19	GR / s	NS NP					.3
		20-27	SBK / cl	FI SS SP					
		28-35	wk / c	FI S P					
		36-47	SBK / sc l	FR SS SP					
3									
4									
5									

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .35
EVALUATED BY: Sparks OTHER(S) PRESENT: J. Johnson
COMMENTS: #2 had some material from lake dredging placed on it
berms to be cut down before S/T installation