Repair

PIN# 4648-31-0767

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Don Scott Kelly DATE 6/27/91 PERMIT NO. ———

PHONE: Business ——— Home 872-7098

LOCATION Beaufort Bay - 150W - TR Bluefield Rd, TL Big Indian Loop TR into Beaufort Bay - to next to last house on L S. R. No. ———

SUBDIVISION NAME Beaufort Bay LOT NO. 16 SECTION OR BLOCK NO. ———

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 2.5

Garbage Disposal Unit	Yes	(✓)	No	(1)	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site Suitable	Yes	(✓)	No	( )	

Character & Porosity of Soil clay - s, f, sl. plastic

Percolation Rate 35'


Topography 2-4%

Depth to Water Table >48"

Rock or other impervious formations None found

Lot Area 20,000 FT²

——— Basement with Plumbing ——— Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 1 - 115' x 3'
Sq. Ft. ——— Linear Ft. ———
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Donald Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: ———

IMPROVEMENTS PERMIT BY ———

COMMENTS: Roof gutters down spouts need to be put in solid pipe and routed across drainfield. S/B was re-level (top 2 lines to big too much)

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 6/27/91

EXISTING SYSTEM CHECKED BY: ——— DATE ———

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold