DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

1 of 2

OWNER: Kirk Sherrill / Ronald Nash APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/4/97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #17 Bearstooth Bay PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	LL 5-10%	0-7"	Brn SCL GR FR						PS .3
		7-20"	Brn C SBK S,P,SE,FI						
		20"-48"	Rd/Brn C/CL SBK SS,SP,SE,F-FR						
2		0-24"	Rd/Brn SBK CL SS,SP,SE,FR						U
		24"-48"	White/Gray Quartz Sand						
		☆ must be Fill							
3		0-24"	Rd/Brn SBK CL SS,SP,SE FR						U
		24"	White/Gray Quartz Sand — Fill Area						
4	L ~10%	0-14"	Brn/Rd-Brn C SBK S-SS,P,SP,E-SE,FI						.2-.25
		14"-27"	Brn C FSBK S,P,SE-E,FI						
		27"-48"	Brn-Yel-Brn SC FSBK S,P,SE,FI w/ some SAP inclus						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION SB-3 — 73' to Rock

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

2 of 2

OWNER: Kirk Sherrill
ADDRESS: _____
PROPOSED FACILITY: _____
LOCATION OF SITE: Lot #17 Bearsfoot

APPLICANT: _____
APPLICATION DATE: _____
PROPOSED DESIGN FLOW (.1949): _____

DATE EVALUATED: 12-20-06
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

1 48 / 25 / 73

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
5	L 11%	0-24"	Brn SBK C/L	S,SS,SP-F	SE, F-FR				1
		24"-48"	Brn-Yel-Brn	C/SC	S,SS,D,SP,F-FR	SE			
6		0-12"	Dk Brn C/L	SBK	SS,SP	SE, FR			PS .3
7		0-22"	Red Brn Cl	SBK	SS,SPSE	FR			
8		22"	White/Grey Sand		Dredge Fill				
53' from Prof PL		Same as 1in		SR-2#	SB-3				
4									

57' from 6 ~~8~~ edge

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____