Peninsula Realty
663-7645
664-6218

IREDELL COUNTY HEALTH DEPARTMENT

13870

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Wm + Judy Ward DATE 1/10/92 PERMIT NO 2L-A-8/9

PHONE: Business _____ Home 704-946-4784

LOCATION Beech Tree Rd, Bramley Sch. TR on Blume, Straight on Beech Tree, TL 2ND Beech Tree Forest to last lots on (L) S. R. No. _____

SUBDIVISION NAME Beech Tree Forest LOT NO. 8+9 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	( )	No	(✓)
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Character & Porosity of Soil P - cl/c
Percolation Rate .3
Topography 2-3%
Depth to Water Table >48"
Rock or other impervious formations None observed

Lot Area 80,000 Ft²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement (SLAB)



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3 @ 133' x 3'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: [signature]

IMPROVEMENTS PERMIT BY Wesley Sparks RS.

COMMENTS: Trenches no deeper than 36" to trench bottom. Drop boxes - Lines must follow slope contour in manner shown on permit here.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold