DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kevin Traynor APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/10/97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Bearsfoot Bay Lot #4 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LL 4%	0-6"	R/Brn C SBK S-PE-SE	F wf	Exp C (probably fill)				PS .25-.3 to
		6-22"	Brn/Mot Brn	CL mF SBK S,SPL SE,FR	w/Indics of SAP				
		22"-48"	Mot Brn SL	SAP FR					
		Would need Profile pits for further evaluation							
2	LL 4%	0-8"	Brn C/CL mSBK SS,SP SE	FR-FI					PS .3 to 48"
		8"-22"	Brn/Mot CL mSBK SS,SP SE	FR					
		22"-48"	Mot Brn CL mAngSAP	(SA) Indics					
			FSBK SS,SP SE	FR					
3	SS 4%	0-12"	Brn SL C/F	FR					PS .3+ 48"
		12"-48"	R/Brn C/F	mSBK SS,SP SE	FR				
4	7% FS	0-12"	Brn/Mot Brn C/M	mSBK SS,SP SE	FR				PS .25-.3 to 24"
		12"-24"	Brn/Mot CL	mSBK SS,SP SE	FR				
		24"-38"	Mot Brn/Brn W. Brn						
		38"-48"	Mot Brn CL	SAP FR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____