3-3:30

IREDELL COUNTY HEALTH DEPARTMENT

(5051)

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Eric Mentzy (Jerry Barnett Builder) DATE 8/13/92 PERMIT NO. 2L-8-A-2

PHONE: Business 664-4044 Home

LOCATION Beech Tree Rd, TR off Brawley School, on (L) at first intersection to Beech Tree Forest. S.R. No.

SUBDIVISION NAME Beech Tree Forest LOT NO. 2 SECTION OR BLOCK NO.

House ☑ Mobile Home ☐ Business ☐ Other

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area ~ 20,000 FT²

Soil Characteristics P - C


Application Rate P - SF, SP, .3

Topography P - Hilly

Depth to Water Table 5 - >48"

Rock or other impervious formations 5 - None observed

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement ____ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 4 @ 100' x 3'

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 12

Water Supply: Individual ☑ NOT DRILLED YET

Public ☐

Installed by

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: X Jerry Barnette

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY Wesley Sparks RS. BEECH TREE RD.

COMMENTS

Keep trenches on slope contours as shown. Trenches no deeper than 36" to trench bottom.

CERTIFICATE OF COMPLETION BY DATE

EXISTING SYSTEM CHECKED BY DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold