IREDELL COUNTY HEALTH DEPARTMENT PIN# 4648-32-4976

12904

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR R+L / Deal Homes DATE 11/13/91 PERMIT NO. 2P-18-A-28

PHONE: Business _____ Home 892-9999

LOCATION Big Indian Loop - Blue sig, TL on Big Indian, Beaufort Bay first lot on (L) S. R. No. _____

SUBDIVISION NAME Beaufort Bay LOT NO. 28 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil cl - scl (sf)
Percolation Rate .3
Topography 2-4%
Depth to Water Table 74"
Rock or other impervious formations None observed

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System Big Indian Loop.

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4 @ 100' x 3'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public ( )

Installed by Rowan Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Drop boxes - trenches no deeper than 36" to trench bottom. Repair space on lower side of drainfield area.

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 11/13/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold