12321

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Stephanie Thwaites DATE July 30, '91 PERMIT NO. 2R-A-17

PHONE: Business _____ Home _____

LOCATION 21 N. TR 1302 (Cornelius Rd.) TR onto gravel road Approx. ¼ mile before I 77 800'± on Right

SUBDIVISION NAME Bertha Byers Estate LOT NO. 4 SECTION OR BLOCK NO. _____ S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site ~~Suitable~~ PS	Yes (✓)	No ( )

Lot Area 2.5 Ac.

Character & Porosity of Soil PS clay
Percolation Rate 2, 4 J
Topography 2 6%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3-4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Stephanie G. Thwaites

IMPROVEMENTS PERMIT BY David R. Hunsucker, RS

COMMENTS: This permit replaces one issued Jan 22, '91

Follow contour with trenches. Trench bottom depth 24-30".

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

Across Road To Septic Tank