DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

ON-SITE WASTEWATER SYSTEM

OWNER: Todd Baney APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/10/04
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Cornelius Est Lot # 42 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Back of Lot	0-5"	Brw SCL	GR FR					PS .25 to 36" LTAR @ 36"
		5"-38"	Rd/Brw C/SC m-w	SBK SS, SP, SE, FI-FR w/ Chroma 2 mottles					
		38-48"	Rd/Brw SC w/						
2	Front	0-11"	Brw SCL	GR FR					PS .3
		11-36"	Rd/Brw C/SC m-w	SBK, SS, SP, SE, FR w/ Some SAP Textures & Mica Flakes					
		36-48"	Rd/Brw/Gry	Brw L SAP					
3	P.V	0-10"	Brw SCL	GR FR					.3 to 32" .25 >32"
		10"-32"	Rd/Brw C/SC m-w	SBK SS, SP, SE, FR w/ Common Mica Flakes					
		32-56"	Rd/Brw C/SC w/	BR to massive FI-FR, SS-SS SP, SE					
4	P.V	0-15"	Brw SCL	GR FR					PS .3+
		15-32	Rd/Brw C/SC m-w	SBK SS	SP, SE, FR				
		32-48	L/SC	SAP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #
COUNTY

LOG OF ON-SITE WASTEWATER SYSTEM

OWNER: Todd Ranson APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 3/10/04
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: Carneal's Ext Lot #43 PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut *Check permit for Lot #44?
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Back	0-8"	Mulch / Top Soil						PS .2 to .25
		8"-48"	R C/sk F; S, P, SE	Wy	some yellow/brown mottles				
2	Back	0-14"	Fill?						PS Tiger Dim .2
		14"-24"	Rd C/Pl m-w SBK	SS, SP, SE, FF	Yel/Brn mottles		(Rubbly Tiger Dim)		
		24"-54"	R C/SL w/ many	S, SP, SE, FF					
3	Back	0-12"	Brn SCL (SA) FR						PS .25
		12"-30"	Rd/Brn C/Pl m-w	SBK SS, SP, SE, FF					
		30-53	R C/SL w/o	massive S-SS, SP, SE					
			Yel/Brn	F-FR w/ many mottles					
4	Front	0-4	Brn, SCL						PS .3
		4-38"	Rd/Brn C/Pl	m-w SBK SS, SP, SE, FR w/ few SM Indus					
			Saprolite	Mica flakes & few to many					
		38"-48"	L SAP	w/ few to many Cl Indus					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: