DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Earlstine Johnson APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: 2BD - 1½BA PROPOSED DESIGN FLOW (.1949): 240 PROPERTY SIZE: 18 AC
LOCATION OF SITE: Farm Hill Rd on (L) just past Musgrove PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	CCL 2-8% upper	0-7	sbk / cl	FI S SP					
		8-13	sbk / h c l	FI S P					
		14-31	sbk / c l	FR S SP					
		32-46	wk sbk / cl SPF	FR S SP	↓ PS < chr	PS	NEXP PS	36"	.25
2	CC lower to (R)	0-5	sbk / lc	FI S P					
		6-32	sbk / c	FI S P	↓ 33" MOTTLE H2O (TOPO)	PS	SEXP ~ VL	32" H2O	—
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): TOPO VERY IMPORTANT
SITE CLASSIFICATION (.1948): PS on (L) side slope

EVALUATED BY: Sparks
OTHER(S) PRESENT: E Johnson