DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Phil Schepens — APPLICANT: ___
ADDRESS: ___ — APPLICATION DATE: ___ — DATE EVALUATED: 1-5-05
PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 360 gpd — PROPERTY SIZE: 2.178 ± ac
LOCATION OF SITE: Lot 7 The Ranches — PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5% L	0-9	wkSBK/gr/sdy	fr sss p					.03
		9-34	mf sbk RC	fr sp sop					
		34-55	wk sbk RCL	fr sss p					
2		0-8	gr-wk sbk sdy	fr sss p					.25
		8-53	mf sbk RC	fr sp-ss sp	SExp few yb mn mottles				
3	5% L	0-5	wk sbk sdy sl	fr					.25
		5-52	mf sbk RC	fr sp SExp	few y/bl mn mottles				
4	7-20-05	0-4	gravel						.25
		4-17	gravelly sdy/c	wk sbk fr sss p					
		17-60	SBK c/cl	fr sss p	S exp				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	LPPPBPS	LPPPBPS
Site LTAR	.25	.25

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DR Hinson
OTHER(S) PRESENT: Old gully now filled with 7-20-05
Had well been put where specified on permit for lot 8 then lot would have been 100% for septic