DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 1-12-03
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 3 - Tanglewood PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	gn-wk sbk brn SL	fr sss p					.3
		9-30	mfsbk RC	fi fr sss p SEXP					
		30-40	(B-C) wk bsk yR cl	fi fr sss p					
		40-67	wk sbk mass yR LSAP	fr sss p					
2		0-3	gn-wk sbk brn SL	fr sss p					.25
		3-21	mfsbk RC	fi sp SEXP					
		21-50	(B-C) wk f-m ABK yR-RG cl/lc	fr sss p common vf-f sap					
		50-68	massive R/gn LSAP	fr sss p					
3		0-8	gn-wk sbk brn SL	fr sss p					.25-.3
		8-19	mfsbk yR-pbrn c/cl	fi fr sss p SEXP				few - common vf-f iron mottles	
		19-40	(B-C) wk f-m ABK yR-RG cl	fr sss p common vf-f sap					
		40-70	massive ybrn-pbrn LSAP	fr sss p					
4		0-18	gn brn SL	fr sss p					.25-.225
		18-50	mfsbk RC	fr sp / SEXP				common ybrn mottles	
		50+	wk sbk gn cl	fr sss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	25% Red.	1 PPBBS
Site LTAR	.225-.25	.225-.25

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DHT
OTHER(S) PRESENT: Phil Schuyler

COMMENTS: ___

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: _____
LOCATION OF SITE: Lot 3 Tankerwood Court. PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5		0-5	gr loamSL	frssop					
		5-10	wk fsbk brn SCL	frssop					
		10-24	mfsbk brn c	frssp	sap common yb mottles				.25
		24-59	wk fsbk gr c/f/k	frssop	common mif sap				
6		0-11	gr loamSL	frssp					
		11-23	mfsbk yr cl	frssop					
		23-45	mf sbk RC	frssop	common yb mottles				.225-.25
		45-66	wk fsbk gr cl	frssop	common mif sap				
7		0-13	gr loamSL	frssp					
		13-43	mf sbk RC	fr ss-ds p sap	common yb mottles				.25
		43-68	wk fsbk gr cl	frssop	common mif sap				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____