ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Phil Schepens / Countrywide
ADDRESS: ___ APPLICANT: ___
PROPOSED FACILITY: SFR APPLICATION DATE: ___
LOCATION OF SITE: Lot 1 The Ranches PROPOSED DESIGN FLOW (.1949): 360gpd DATE EVALUATED: 1-6-05
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY SIZE: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut PROPERTY RECORDED: ___
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	6% S	0-3	wk sbk brn sl gr	fr					
		3-27	mk sbk RC	fr ss sp SCP					
		27-56	wk fsbk RC/cl	fr sp-ss sp	few mic sap				3
2		0-3	wk sbk DRK brn sl	fr ss sp					
		3-19	mk sbk RC/cl	fr ss sp SCP					
		19-52	wk fsbk gr cl	fr ss sp					3
3		0-12	mk sbk RCL	fr ss sp					
		12-37	wk fsbk RC/cl	fr s sp SCP	few mic sap & g. w. roots				
		37-58	wk fsbk RC/cl	fr ss sp	common mic sap				3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	25	25
System Type(s)	Gravity	LPPBRS
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): S
EVALUATED BY: ___
OTHER(S) PRESENT: ___