SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____

RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-29-01

OSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

ATION OF SITE: Lot 52 Whitshire Creek PROPERTY RECORDED: _____

ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
(1)	0-10	gr lsvl sl/sl	fr					.3
	10-30	sbk, rc/c	fr sss sp sap					
	30-52	mk fsbk rcl	common/mod sap + wR	Pf-fr sss p				
(2)	0-6	gr lsvl sl	fr sss p					.3
	6-27	sbk r c	fi sp					
	27-57	mf sbk yrcl	fr sss p	many mic quartz vn				
(3)	0-21	smk RC	Fi SP					P5
	21-68	mfsbk RCL	Fri sss p	many SAP				.3
(4)	0-6	wsmk BSL	Fri sss p					P5
	6-24	smk RC/L	Fri sss p					.3
	24-43	mwsmk YRCL	Fri sss p					
	43-59	m SL SAP	Fri MS NP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		
TAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____