DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: 3F A22
PROPERTY RECORDED: ___
COUNTY: IREDELL

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: MICHAEL MOORE OWNER: ✓ AGENT: ___ PHONE: 528-5258
ADDRESS: RT 1 BOX 203 APPLICATION DATE: 6/22 DATE EVALUATED: 6/25/93
TROUTMAN, NC. 28166 PROPOSED FACILITY: 3BO M H
PROPERTY SIZE: ~ 40 AC
LOCATION OF SITE: CARLYLE RD (L) OFF FLOWE HOUSE LOOP TL CARLYLE ON (R) BEFORE JASMINE
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	S 5-9%	0-7	NC / L	1:1	S	No	P		
		8-15	M, SM, N / C	1:1	S	No	P	No	
		16-23	S, H, SS / C	1:1	S	No	P		
		24-41	S, SM, SS / C	1:1	S	No	P	No	.25-.3
2	S 6-8%	0-11	NC, M, L / L	1:1	S	No			
		12-19	S, F, SP / C	1:1	S	No	P	No	
		20-23	S, F SP / C	1:1	S	No	P	No	BRIGHT
		23-39	SS, SP, SM / C	1:1	S	P	S	No	.3-.4
		40	HIT ROCK						
3									
4									
5									

AVAILABLE SPACE (.1945) S SITE CLASSIFICATION (.1948): P SITE LONG-TERM ACCEPTANCE RATE: .4 & 2
EVALUATED BY: SPARKS OTHER(S) PRESENT: MIKE MOORE
COMMENTS: SITE 2 - LESS STICKY, LESS FIRM BETWEEN 19-36" DEPTH, NOT AS FIRM UPSLOPE - BETTER DRAINED / SITE 1 AS REPAIR AREA

ROAD
PWD LINE