DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 3-9-04
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 9 Tanglewood PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Lot 9 proper	0-26	SBK rc/cl	fr sps/sp/p					.25-.3
		26-52	massive	fr/L sp/p fr ss/p					
2	Lot 9 proper	0-22	ms sbk rc/cl	fr sp/sp/p	few ind sap				.25-.3
		22-55	w sbk-massive	fr/L sp/p fr ss/p	few ind PL				
3	Lot 9 proper	0-22	w sbk rc/cl	fr sp/sp/p					.3
		22-50	w sbk-massive	fr/L sp/p fr ss/p					
4	SFE lot 1	0-23	w sbk rc/cl	fr sp/sp/p	few ind PL				.3
		23-42	massive	fr/L sp/p fr ss/p					
		-67		SL sp/p fr ss/p					
			Discharge						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___