4649 444 4307

11915

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Billy L Reeves DATE 1/20/93 PERMIT NO. 2R 3A1

PHONE: Business _____ Home 892-7460

LOCATION Fern Hill Rd, 1.15 N TL Flower House (L) Rankin Hill R Fern Hill ~.3 mile to 4th driveway (R), 1st mailbox (L) S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☐ Mobile Home ☑ D/W Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area ~ 3Ac

Soil Characteristics P - C/C TRANS (SL)


Application Rate P - .3-.35 (P, SS, WK SBK)

Topography P - 3-6%

Depth to Water Table S > 48"

Rock or other impervious formations S < @ 36" & > 48" TO TRANS

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 4 @ 85' x 3'

Sq. Ft. 1020 Linear Ft. 340

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by Larry Powell

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS Keep vehicles off end of drainfield. Drop Boxes used in lieu of D/B - Tight for available area due to large drainage area that bisects left rear corner of this lot

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 1/20/93

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

11915

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR BILLY L REEVES DATE 9/2/92 PERMIT NO. 2R 3A 1

PHONE: Business _____ Home 892-7460 (664-2611)

LOCATION FERN HILL RD. & 115N TL ON FLOWER HOUSE TL ON RANKIN HILL TR ON FERN HILL, ~.2 mile TR on gravel drive ~ 500' from FERN HILL (E) S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☐ Mobile Home ☑ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area ~ 3 AC

Soil Characteristics P - C/C TRANS


Application Rate P - .35 (SF, SS)

Topography P - 30%

Depth to Water Table S - >48"

Rock or other impervious formations P - 48" SAPROLITE

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 4 @ 85' x 3'

Sq. Ft. 1020 Linear Ft. 340

Depth of Stone in Lines 12"

Water Supply: Individual ☑ NOT DRILLED YET

Public ☐

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: Betty L. Reeves

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY Wesley Sparks RS

COMMENTS Trenches no deeper than 36" to trench bottom. Follow slope contour closely. Drop Boxes w/ one box per drainline as shown here. No changes without Health Dept. approval, tight for useable space

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold