DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 4-16-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 17 Mason Trail PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	wk fgr sbk rbnsl L	fr sssp					.3
		6-18	SAB RC	fr sssp					
		18-70	m-wk fsbk/gr cl	fr sssp few common in ssp					
2		0-23	sab rc	fr sp					.3
		23-65	rcl	fr sssp common in ssp					
3		0-3	wk sab rbnsl	fr sssp					.3
		3-15	sbrc	fr sssp ssp					
		15-68	m-wk fsbk/gr cl	fr sssp few-common ssp increasing w/ depth					
4		0-8	BAL HO	fr SAP					.3
		8-40	SAH CL	fr SSSP common SAP					
		40-64	LSAP	fr SSSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

3) 0-63 MWFSAK RCL fr SSSP few
.3

(169.86'TOTAL)
19.93'
(160.11'TOTAL)
140.18'
(180.29'TOTAL)
40.11'
S02°04'42"E
6.23'
C.M.
CONTROL CORNER
S02°04'42"E
257.53'
0.82 ACRES
LOT 17
199.88'
S00°29'59"W
0.83 ACRES
LOT 18
203.51'
S00°29'59"W
35' SETBACK
(231.02'TOTAL)
14.93'
S85°07'25"E 180.53'
LARAMIE COURT
45' PU
C18
35.53'
N85°07'25"W 176.30'
(231.02'TOTAL)
C19
C24
35' SETBACK
138.00'
S02°04'42"E
C.M.
CONTROL CORNER
0.72 ACRES
LOT 24
199.86'
S01°47'30"E
0.80 ACRES
LOT 23
199.75'
S01°30'17"E
175.29'
175.29'