4649731901

10639

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Timothy W. Marshall DATE Mar 15, 1990 PERMIT NO. 2R-A-3pt.

PHONE: Business _____ Home _____

LOCATION 115-21N TL 1312 (Flowerhouse Loop) TL Rankin Hill Rd (1311) on left corner lot with 1310 (Parkertown Rd.) S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 5 No. Bathrooms 3½

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area 7.145 ac

Character & Porosity of Soil PS clay


Percolation Rate ~.4

Topography 2-4%

Depth to Water Table 4' +

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing _✓_ No Basement



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:

No. of Lines 5

Sq. Ft. 1500 Linear Ft. 500

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Mack Sherrill

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Well not installed @ time of final

CERTIFICATE OF COMPLETION BY Sam Ingram EHS DATE 3/15/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold