DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 4-16-02
LOCATION OF SITE: Lot 2 Magee Forest PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-3	gr fsl/scl	frssp					.25-.3
		3-21	SBK-R sc	fi ssp					
		21-60	wk fsbk yr cl	fi-frssp	common mi lsp				
2		0-42	wk sbk cl	common mi fr sp					.2-.25
		42-72	AB Bysic	fi-frsp	mixed 42"+ chr 2				
3		0-40	sbk cl	fr ssp	few common mi lsp				.3
		40-69	wk sbk yr LSP	fr ssp					
4		0-36	wk sbk cl	fr ssp	common mi lsp				.3+
		36-65	LSP	fr ssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

(5) 0-16 sbk rc fi fr ssp
16-42 m-sbk rc fr ssp / common mi lsp .3
42-65 LSP fr ssp

CURVE	RADIUS	ARC LENGTH	CHORD LENGTH	CHORD BEA
C1	172.50'	33.36'	33.31'	N54°13'49"
C2	127.50'	85.44'	83.85'	S67°53'14"
C3	172.50'	109.79'	107.95'	S68°51'02"
			21.41'	N67°33'49"