ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 4-17-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 28 Magnolia Trail PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		6-4	gr brn sl/scl						.3
		4-24	SAB RC	fi sp sapo					
		24-35	w-wk fsab yR	CL fi sss sp common in fsap					
		35-66	L sap	fr sss sp					
2		0-3	gr brn sl/scl						.3
		3-23	SAB RC/CL	fr sp-ss sp sapo					
		25-60	wk fsab yR	CL/L fi sap common in fsap					
3		0-13	gr brn scl	fr sss sp					.25
		13-36	SAB RC	fi sp sapo					
		36-59	wk fsab yR	L sap fr sss sp					
4		0-13	wk SAB brn scl	fr sap					.2 @ <36"
		13-36	wk SAB RCL	fr sss sp					
		36-60	wk MB	RC fi sp common fine of ch 3/4 mottles	36" to fragipan				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

#5 0-23 gr-wk sab brn scl fr sap
23-67 wk MB gybrn C fi sp mica common manganese coatings
LTAR .1

SITE

INITY MAP (N.T.S.)

