ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 6-17-02
LOCATION OF SITE: Lot 26 Magnolia Road PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-16	A fsl scl	frssp					PS .25-.3 @ 44"
		16-32	Sub Bc	fr sp					
		32-44	m-f Sub Bcb	few-common gravel & sl sap	fr ssp				
		44-65	wk f Sub	cl sap	fr ssp sap/mpd?				
					many birch relic - few drainage?				
2		0-8	gr brn sl	fr ssp					.3
		8-25	Sub Bc	fr sp	soft				
		25-58	m-wk f Sub yel cl	fr ssp	Sap few common mic sap				
3		0-3	compacted gr cl	fi-fr ss sp					.3
		3-19	Sub B cl cl	fi-fr					
		19-40	wk f Sub B cl	common mic sap fr ss sp					
		40-66	wk f Sub yel L Sap-SL Sap	fr ss sp					
4		0-12	compacted cl cl	fi-vfi					.3
		12-46	Sub Bc	fr ss sp	common mic sap > 36"				
		46-66	L Sap	fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

LTAR .3 - .82 (Hall) Wendell Hall Grading - Hwy 64 Cooper

MAGIC FOREST PHASE 1
PRIMESTAR PROPERTIES, INC.
PB.39 PG.40

