07874

IREDELL COUNTY HEALTH DEPARTMENT 4649764546

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Leigh Earley DATE Feb 15, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N TL 1312 (Howes House Loop) TL 1311 (Rankin Hill Rd.) TL into Palomino Park S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 63 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~	Yes (✓)	No ( )	

Lot Area ~20000 s/f

Character & Porosity of Soil Clay


Percolation Rate 2@35

Topography G-Sa

Depth to Water Table 44

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 675+ Linear Ft. 225+

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY A.C. Pierce

COMMENTS: old system ever repaired, will need to change hookup of last drop box.

CERTIFICATE OF COMPLETION BY D.R. Hinson, R.S. DATE Feb 15, '88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold