IREDELL COUNTY HEALTH DEPARTMENT

4649764696

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Craver DATE 5/26/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21N, Lf on Flower House, Lf on Rankin Hill, Lf into Palomino Park


SUBDIVISION NAME Palomino Park S. R. No. _____

LOT NO. 62 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	2 0.4 gpd/ft²
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
Lot Area 20,000 ft²			Rock or other impervious formations	none observed



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓) To be drilled
Public ( )

Installed by Chaffin Farm

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

RCC System

IMPROVEMENTS PERMIT BY David K. Hinson RS

COMMENTS: Keep well 50' minimum from septic system. Layout change OK by KS 5/26/87

CERTIFICATE OF COMPLETION BY _____ DATE 5/26/87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold