IREDELL COUNTY HEALTH DEPARTMENT 4649 76 6938

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Oaler DATE 3/6/87 PERMIT NO.

PHONE: Business Home

LOCATION 115 N Lf on Flower House Lf on Rankin, Lf on Palomino Park, Take First Drive to Lf. Lf again + Lot on Rt


SUBDIVISION NAME Palomino Park LOT NO. 60 SECTION OR BLOCK NO. S. R. No.

House ( ) Mobile Home (✓) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clayey	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	24 spm/1"	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+	
Lot Area			Rock or other impervious formations	None observed	

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 900
Depth of Stone in Lines 12

Water Supply: Individual ( )
Public (✓)

Installed by Wayne Parks

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY David R Hinson.

COMMENTS: 1 PBox used, OC by KS prior to installation,

CERTIFICATE OF COMPLETION BY [signature] DATE 3/6/87

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold