SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

PROPERTY ID #: _____
COUNTY: _____

OWNER: John Blankenship APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 1/16/20
LOCATION OF SITE: Palomino Pk Lot #69 PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-28"	RCL mSBK	S-SS, P-SP, SE	F-FR				PS, .3, at 28-48"
	28-48"	RCL m-wSBK	SS, SP, SE, FR	w/Some Mica				
	0-28	RCL mSBK	S-SS, P-SP, SE	F-FR w/Few Yel/Brn Mottles (may be relict)				PS, .3
	28-48	RCL wSBK	SS, SP, SE	FR w/Few Yel/Brn Mottles				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Trench Space (.1945)		
Trench Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____