4649-76-9466

14362

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Jeffery McClease DATE 4/10/92

PHONE: Business _____ Home 933-6615 PERMIT NO. 4L-3-A-78

LOCATION Rankin Hill Rd; TL off 1st Flower House Lp.

SUBDIVISION NAME Palomino Park LOT NO. 78 SECTION OR BLOCK NO. _____ S.R. No. _____

House ☐ Mobile Home ☑ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 20,000 FT2

Soil Characteristics P - C (b, fine structure)


Application Rate P .3

Topography P - 3%

Depth to Water Table 5' - >48"

Rock or other impervious formations 5 None observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 4 @ 100' x 3'

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by Keith Spease

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS Drive must enter on (R) side of lot as shown here.

CERTIFICATE OF COMPLETION BY Wesley Sparks

EXISTING SYSTEM CHECKED BY _____ DATE 4/10/92

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS DATE _____

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

1 4362

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Jeffery McCleese

PHONE: Business _____ Home _____ DATE March 30, '92 PERMIT NO. 4L-3-A-92

LOCATION 115-21 N, TL 1312 (Flower House Loop) TL 1311 (Rankin Hill Rd.) TL into Palomino Park bear right, on left before road merges

SUBDIVISION NAME Palomino Park LOT NO. 78 S.R. No. _____ SECTION OR BLOCK NO. _____

House ☐ Mobile Home ☑ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☐ No ☑

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 720,000 ft2

Soil Characteristics Pimps clay


Application Rate .3

Topography 2-4%

Depth to Water Table 74'

Rock or other impervious formations numerous rhizomorphs

NONE OBS.



☑ No Basement ☐ Crawl Space

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 24"

Water Supply: Individual ☑ Public ☐

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: Jeffery McCleese

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

PROVEMENT PERMIT BY David R. Hinson, RS.

MENTS Follow contour with drainfield. 24" trench bottom depth. Can use drop boxes if desired.

FICATE OF COMPLETION BY _____ DATE _____

NG SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

S VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false ion is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold