4649-76-9989

13134

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Paul Wilkins DATE 8/19/91 PERMIT NO. 4E-5-A-74

PHONE: Business _____ Home _____

LOCATION _____

S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 74 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	(✓)	No	(✓)
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Character & Porosity of Soil P-firm, SA
Percolation Rate 3
Topography Lots
Depth to Water Table 74811
Rock or other impervious formations None found

Lot Area 20,000 SQ FT

~~Basement with Plumbing~~ ~~Basement without Plumbing~~ No Basement



Plot of System STREET

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3 @ 130 x 3'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Mike Leazer

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Tank depth 24" – S/T location changed to accomodate pool site. Repair area at back of property.

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 8/19/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

13134

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Paul Williams DATE July 24, 91 PERMIT NO. 4E-3-A74

PHONE: Business _____ Home _____

LOCATION 115-21 N. TL 1312 (Flower House Loop) TL 1311 (Rankin Hill Rd)
TL into Palomino Park 1/4 mile on left

SUBDIVISION NAME Palomino Park LOT NO. 74 S. R. No. _____

DW


House ( ) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes ( ) No ( )
Site Suitable PS Yes ( ) No ( )
Lot Area 2+ AC 210' Rock or other impervious formations none obs.

Character & Porosity of Soil PS clay
Percolation Rate 43
Topography Lot Line N 69 E
Depth to Water Table 3 ft

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Paul Williams

IMPROVEMENTS PERMIT BY Jason R. Henson, RS

COMMENTS: Follow contour. Maximum trench bottom depth of 24".

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold