IREDELL COUNTY HEALTH DEPARTMENT 4649 77 7101

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Craver DATE 8-20-87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TL 1312 (Flower House Loop) TL 1311 (Rankin Hill Rd.) ~1/2 mi on left. TL on dirt TL on next Rd. on left S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 59 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area ~30,000 ft²

Character & Porosity of Soil clayey
Percolation Rate ~1 gpd/ft²
Topography Top
Depth to Water Table 4'+
Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System N.T.S.

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Wayne Potts

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C Price

EXISTING SYSTEM CHECKED BY: _____ DATE 8-20-87

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

10-45

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Craver DATE Mar 20, 87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21N Rt 1312 (Hower Home Loop) Rt 1311 (Rankin Hill Rd.) ~½ mile on left

SUBDIVISION NAME Palomino Park LOT NO. 59 SECTION OR BLOCK NO. _____ S. R. No. _____


D.W.

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	~.40	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	44	
Lot Area ~30000 ft²			Rock or other impervious formations	none obs.	

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

✓ Signed: John Craver

IMPROVEMENTS PERMIT BY Jack R. Hinson R.S.

COMMENTS: Install drainfield shallow (~12" cover) Can use 4- 75' ditches if needed.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold