4649 ++ 9881

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR REBECCA ANN MAYHEW DATE 8/16/88 PERMIT NO. 18A

PHONE: Business _____ Home 892-5353

LOCATION 21 N TL FLOWERHOUSE LP. TL RANKIN HILL TL PALOMINO TL SORRELL TL CAT AT END S. R. No. _____

SUBDIVISION NAME PALOMINO LOT NO. 52 SECTION OR BLOCK NO. 4E-3-A-52

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms _____

Garbage Disposal Unit Yes ( ) No ( )

Auto. Dishwasher Yes ( ) No ( )

Auto. Wash. Machine Yes ( ) No ( )

Site Suitable Yes ( ) No ( )

Lot Area _____

Character & Porosity of Soil clayey


Percolation Rate .35

Topography 6-15%

Depth to Water Table 4'+

Rock or other impervious formations none

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Cul-de-sac

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 675 Linear Ft. 225

Depth of Stone in Lines 12"

Water Supply: Individual (x)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Andrew C. Quinn

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Quinn DATE 8/16/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

8-99

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rebecca Ann Mayhew DATE 7/18/88 PERMIT NO. _____

PHONE: Business _____ Home 892-5353

LOCATION 21N TL Flowerhouse Loop TL Rankin Hill TL Palomino Rd. TL Sorrell TL Colt. At end. S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 52 SECTION OR BLOCK NO. 4E-3-A-52

House ( ) Mobile Home (✓) D.W. Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area ~1¼ ACRE 20000 ft²

Character & Porosity of Soil clayey


Percolation Rate ~.35gpd/ft²

Topography 690

Depth to Water Table 4'+

Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NOT TO SCALE

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 675 Linear Ft. 225

Depth of Stone in Lines _____

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Roger & Mayhew

IMPROVEMENTS PERMIT BY Andie C Rice

COMMENTS: Installed SHALLOW lines and on contour 12" – 16" cover over drainfield.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold