464985 0946

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR James & Diane Freeland DATE 9/20/88 PERMIT NO. 18A

PHONE: Business _____ Home 528-4261

LOCATION 21N TL Flowerhouse Loop TL Rankin Hill TL Palomino On R. ~ 1/4 mile.

SUBDIVISION NAME Palomino LOT NO. 7 S. R. No. _____

SECTION OR BLOCK NO. 4E-3-A-7 BARRINGER

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Character & Porosity of Soil Clayey

Percolation Rate .25 gpd/ft²


Topography 6%

Depth to Water Table 4'+

Rock or other impervious formations none observed

Lot Area 1 3/4 ACRE

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 810 Linear Ft. 270

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Wayne Ellen

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____ A.C.G.

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andre C. Pierce

EXISTING SYSTEM CHECKED BY: _____ DATE 9/20/88

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold