VISION OF ENVIRONMENTAL HEALTH
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICATION DATE _____

DDRESS: _____ DATE EVALUATED: _____

ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: Lot 46 maple Lake St PROPERTY RECORDED: _____

ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

/ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

(PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	BSCL GR	fri SSSP SaP					PS -3
		4-33	RCL MFSAN	fri SSSP SaP					
		33-53	L/SCLSAP MSAN	fri SSSP					
2		0-6	BSCL GR	fri SSSP SaP					PS -3
		6-24	RC SAN	fi SP SaP					
		24-60	RCL MFSAN	fri SSSP SaP many SAP					
3		0-4	BSCL GR	fri SSSP SaP					PS -3
		4-21	RC SAN	fi SP SaP					
		21-58	RCL MFSAN	fri SSSP SaP few SAP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		


OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

COMMENTS: _____



DEWARD E. ERVIN
DB.937 PG.2071
PARCEL ONE