11633

IREDELL COUNTY HEALTH DEPARTMENT

4649 87 3613

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jeff Lancaster DATE 7/23/90 PERMIT NO. 4E3-A-49+50

PHONE: Business _____ Home _____

LOCATION 115-21N TL 1312 (Flower House Loop) TL 1311 (Rankin Hill Rd.) TL into Palomino Park TL 1st Street .3mi on Left S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 49-50 Combined SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other Area of drainfield

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes	( )	No	(✓)	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site ~~Suitable~~	Yes	(✓)	No	( )	

Character & Porosity of Soil: ~~Sandy~~ clay

Percolation Rate: .3 - 0/35

Topography: ~6% 3%

Depth to Water Table: _____

Rock or other impervious formations: none obs.

Lot Area ~1 ac


_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement

1000 PT

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )



Plot of System

Installed by Darrell Orbison

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF ~~COMPLETION~~ Operation BY Sam Ingram EHS DATE 7/23/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold