02 8941

4649 87 4036

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Patsy Coffey DATE June 21, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 1312 (Hoover Home Lp.) TR 1311 (Rankin Hill Rd.) TR into Palomino Park 1st Farmington Rt S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 15 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	~.3	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	4-6%	
Site ~~Suitable~~ PS	Yes (✓)	No ( )	Depth to Water Table	44	
			Rock or other impervious formations	none obs.	

Lot Area ~2 Ac

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 810 Linear Ft. 270
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Wayne Eller

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH Neighborswell

COMMENTS: _____

CERTIFICATE OF COMPLETION BY W. R. Hamm Jr. S. DATE June 21, '88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold