10285

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Timothy Pritchard DATE Aug 23, 89 PERMIT NO. 4E-3A-20

PHONE: Business _____ Home _____

LOCATION 115-21N TL 312 (Flower House Loop) TL 1311 (Rankin Hill Rd.) TL into Palomino Park on Right

SUBDIVISION NAME Palomino Park LOT NO. 2642 SECTION OR BLOCK NO. _____ S. R. No. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site ~~Suitable~~ PS	Yes (✓)	No ( )

Lot Area ~2.7Ac

Character & Porosity of Soil Clay


Percolation Rate ~103

Topography ~6%

Depth to Water Table 47+

Rock or other impervious formations none obs.

_____ Basement with Plumbing Repair Area Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by D. Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Upper 2 lines deeper in spots than specified on imp. permit but soil looked OK there. DRH

CERTIFICATE OF COMPLETION BY DR Hinson, RS DATE 8-23-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold