08577

4649879623

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Bruce Harmon DATE May 9 '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 No. Rt 131 (Flower House Fork) Rt Rankin Hill Rd. (1311) Rt Palomino Park Rt Sowell ¼ mi on left S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 45 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~	Yes (✓)	No ( )	

Character & Porosity of Soil clay
Percolation Rate 2-4
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations some obs.

Lot Area ~½ Ac

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY ACP

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 5-9-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

85-77

24:30

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR BRUCE HARMON DATE 4/11/88 PERMIT NO. _____

PHONE: Business _____ Home 663-0128

LOCATION 21N TL Flowerhouse Loop TL Rankin Hill Rd. TL Palamino Park TL SORRELL 1/4 mi on L.

SUBDIVISION NAME Palamino Park LOT NO. 45 S. R. No. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes ( )	No (✓)
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable P.S.	Yes (✓)	No ( )

Lot Area 20000 ft² ⇒ 7/10 ACRE

Character & Porosity of Soil Clayey ↑ Imp. P.M.
Percolation Rate ~ 4 gpd/ft²
Topography 40% ↓
Depth to Water Table 4'+
Rock or other impervious formations none observed

_____ Basement with ~~Plumbing~~ _____ Basement without Plumbing ✓ No Basement



Plot of System N.T.S

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Emory Harmon

IMPROVEMENTS PERMIT BY Andrew C Price

COMMENTS: Set tank shallow and keep lines shallow and level.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold